



Inspection Report

To: Bill McGraw (Cheswick Generating Station)
From: Richard Southorn, P.E., P.G.
Re: Cheswick Ash Disposal Site – Annual CCR Unit Inspection Report
Inspection Date: October 21, 2019
Report Date: January 16, 2020

INTRODUCTION

Title 40 Code of Federal Regulations (CFR) Part 257 addresses, in part, the management of Coal Combustion Residuals (CCR Rule, or Rule) in regulated units, including landfills. Specific to §257.84(b) of the Rule, existing and new CCR landfills must be inspected on an annual basis by a qualified professional engineer. For the Cheswick Generating Station (operated by NRG Power Midwest LP), this inspection requirement applies to the existing Cheswick Ash Disposal Site (Ash Disposal Site). In support of this obligation, Mr. Richard Southorn (a qualified professional engineer with Aptim Environmental & Infrastructure, LLC [APTIM]) conducted an on-site inspection of the Ash Disposal Site on October 21, 2019. The findings from this annual inspection are summarized in the remaining sections of this correspondence.

As required, this report will be placed in the Cheswick facility's operating record per §257.105(g)(9), noticed to the State Director per §257.106(g)(7), and posted to the publicly accessible internet site per §257.107(g)(7). Placement of the prior annual inspection report into the facility's operating record was accomplished on January 16, 2019. Per §257.84(b)(4), the current report will be entered into the facility's operating record no later than January 16, 2020.

BACKGROUND

The Ash Disposal Site is a captive landfill used for the disposal of CCR materials and other Pennsylvania residual wastes generated at the Cheswick Station, and is operated/maintained in accordance with Pennsylvania Department of Environmental Protection (PADEP) Solid Waste Permit No. 300720. Active operations are ongoing in the South Valley (Phase I; 51 acres), while the North Valley (Phase II; 31 acres) remains as an unpermitted potential future phase within the Solid Waste Permit boundary. If ever constructed, the North Valley would be considered a new CCR Landfill per the Rule.

Construction of the South Valley commenced in 1980 and disposal of CCR materials began in 1982. When ultimate development conditions are reached, the final upper surface elevation of South Valley will be at approximately 1,200 feet mean sea level (ft. MSL). The active fill area is generally level and is estimated to be at approximate average elevation 1,110 ft. MSL, based on observed filling conditions at the time of inspection.

With respect to the Ash Disposal Site, APTIM's evaluation has focused on the following items as outlined in §257.84(b)(1)(i-ii):

- *A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record; and*
- *A visual inspection of the CCR unit to identify signs of distress or malfunction.*

Specific to APTIM's preparation of the annual inspection report, and per §257.84(b)(2) (i-iv), the following aspects have been addressed:

- *Any changes in geometry of the structure since the previous annual inspection;*
- *The approximate volume of CCR contained in the unit at the time of the inspection;*
- *Any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit; and*
- *Any other change(s) which may have affected the stability or operation of the CCR unit since the previous annual inspection.*

OPERATING RECORDS REVIEW

Principal items reviewed as part of this year's inspection included, but were not limited to: Design Drawings, 2018/2019 Weekly and Periodic Landfill Inspection Reports that have been completed since the 2018 Inspection, 2018 Annual Landfill Operations Report, and Solid Waste Permit No. 300720. During the site inspection, Mr. Southorn interviewed facility personnel (Mr. Bill McGraw) to verify the information contained within the operating record.

Environmental Control System Overview

- i. Leachate Collection System
 - a. The South Valley disposal area has a gravity underdrain system. This system consists of a below-grade piping network that facilitates leachate conveyance ultimately for treatment at the Monarch Mine Dewatering Plant (MMDP). Treated effluent from the MMDP is discharged to Little Deer Creek via Outfall 002 in accordance with the Cheswick Station's National Pollutant Discharge Elimination System (NPDES) Permit.
- ii. Stormwater Management
 - a. "Non-contact" stormwater from the South Valley disposal area is routed (via NPDES-permitted perimeter drainage channels) to the sedimentation pond located at the base of the landfill.
 - b. "Contact" stormwater from within the active disposal area is collected in the leachate underdrain system and routed for treatment in the MMDP as described above.

iii. Cover System

- a. The eastern slope and portions of the northern and southern slopes of South Valley have final cover and established vegetation. The final cover system on the slopes includes benches to dissipate energy build-up and reduce erosion from stormwater run-off.

Summary of Landfill Construction

As previously noted, the active fill area is generally level and is estimated to be at approximate average elevation 1,110 ft. MSL, based on observed filling conditions at the time of inspection. Exterior slopes have a final cover in place along with well-established and properly maintained vegetation.

Review of Prior Inspections

- i. Weekly inspections: A review of weekly inspections has concluded that no significant deficiencies occurred at the facility that required remedial actions.
- ii. Annual inspections: A review of the previous annual inspection report has determined that there were no deficiencies or releases, actual or potential structural weaknesses, or concern to the stability of the land form. All environmental control systems were in good operating condition and functioning as intended.

CCR Disposal

Approximately 3,191,955 tons of CCR had been disposed in the landfill through December 2018. Approximately 53,083 tons of CCR were disposed in 2019, resulting in a total disposed volume of 3,245,038 tons of CCR.

SITE INSPECTION

The site inspection was performed on October 21, 2019 by Mr. Southorn, during which time efforts were focused on identification of standard geotechnical signs of distress or malfunction. Specific aspects such as slumping at the toe of slope, tensile cracking, abnormal or excessive erosion on the side slopes, slope bulging, and groundwater/surface water seepage or ponding were assessed. If present, these readily visible signs are potential indicators of structural weakness of the CCR Landfill unit.

Visual Signs of Distress or Malfunction

No visual signs of distress or malfunction were observed during the inspection. Stormwater drainage features, slope appearance and stability, leachate conveyance mechanisms, and overall site conditions were assessed. Closed portions of the South Valley exhibited well established vegetative cover.

Review of Environmental Control Systems

With no evidence to the contrary, the environmental control systems at South Valley are believed to be in good operating condition and functioning as intended. At the time of the inspection, leachate and stormwater conveyance systems were operating as designed.

Review of Previously Recommended Actions

No corrective actions were required based on the findings of the 2018 Annual Inspection. Recommendations were limited to the continued operation and maintenance of the facility and maintaining access to closed portions of the landfill for inspection purposes. These recommendations were found to have been followed, based on site conditions and the review of weekly inspection logs.

CONCLUSIONS

Changes in Geometry

CCR material placement has progressed in the active disposal area throughout this year. As of the date of the inspection, fill elevations in the active disposal area were at approximately 1,110 ft. MSL. Changes in geometry are limited to the elevation increase of the active disposal area.

In-Place CCR Disposal Quantities

Approximately 3,191,955 tons of CCR had been disposed in the landfill through December 2018. Approximately 53,083 tons of CCR were disposed in 2019, resulting in a total disposed volume of 3,245,038 tons of CCR.

Appearances of an Actual or Potential Structural Weakness of CCR Unit

At the time of inspection, there were no signs of distress or malfunction that would indicate actual or potential structural weakness at South Valley.

Changes that May Affect the Stability or Operation of the CCR Unit

There have been no changes to the South Valley area that pose a threat or concern to the stability of the land form.

RECOMMENDATIONS

1. Continue operation and maintenance in the active areas as currently performed.
2. Ensure adequate access to the closed portions of the landfill to maintain the ability to perform weekly visual site structural inspections.

There were no deficiencies or releases identified during the annual inspection that required the owner or operator to perform corrective actions per §257.84(b)(5).


PROFESSIONAL ENGINEER'S CERTIFICATION

In accordance with §257.84(b) of the Rule, I hereby certify based on a review of available information within the facility's operating records and observations from my personal on-site inspection (including the photographs contained in Attachment 2), that the Cheswick Ash Disposal Site does not exhibit any appearances of actual/potential structural weakness that would be disruptive to the normal operations of the South Valley CCR Unit. The unit is being operated and maintained consistent with recognized and generally accepted good engineering standards and practices.

Certified by: _____

Date: _____

RS
1/16/2020



Richard Southorn, P.E., P.G.
Professional Engineer Registration PE085411
Aptim Environmental & Infrastructure, LLC


ATTACHMENTS

1. Site Map
2. Inspection Photo Log

REFERENCES

1. 2018 Cheswick Generating Station Annual Landfill Operations Report.
2. Weekly and Periodic Landfill Inspection Reports 2018/2019.
3. 40 Code of Federal Regulations, Part 257.
4. Solid Waste Permit No. 300720


Attachment 1
Site Map



LEGEND

← 2019 ANNUAL INSPECTION PHOTOGRAPH (ARROW DENOTES DIRECTION OF VIEW)

REV. NO.	DATE	DESCRIPTION




APTIM Environmental & Infrastructure, LLC

APTIM Environmental & Infrastructure, LLC has prepared this document for a specific project or purpose. All information contained within this document is copyrighted and remains intellectual property of APTIM Environmental & Infrastructure, LLC. This document may not be used or copied, in part or in whole, for any reason without expressed written consent by APTIM Environmental & Infrastructure, LLC.

**CHESWICK GENERATING STATION
SPRINGDALE, PENNSYLVANIA**

PHOTOGRAPH LOCATION MAP

DRAWN BY: BWM APPROVED BY: RDS PROJ. NO.: 631011035 DATE: JANUARY 2020

Attachment 2
Photo Log

Image: 3643
Date: 10/21/2019
Time: 1:20 PM
Direction: Southeast

Description:

Sedimentation Pond.
Healthy vegetation on pond sideslopes. No trash or debris noted on water surface or in surrounding vegetation.



Image: 3645
Date: 10/21/2019
Time: 1:21 PM
Direction: West

Description:

North non-contact water channel (at Outfall 010) inlet to Sedimentation Pond looking upslope. Clear of debris. Functioning as intended.



Image: 3649
 Date: 10/21/2019
 Time: 1:22 PM
 Direction: North

Description:

Sedimentation Pond.
 Healthy vegetation on pond sideslopes. No trash or debris noted on water surface or in surrounding vegetation. Spillway is clear of obstructions. No cracking or evidence of structural damage in outlet structure or spillway.



Image: 3651
 Date: 10/21/2019
 Time: 1:23 PM
 Direction: South

Description:

South non-contact water channel (at Outfall 011) inlet to Sedimentation Pond looking upslope. Clear of debris. Functioning as intended.



Image: 3653
Date: 10/21/2019
Time: 1:25 PM
Direction: West

Description:

North non-contact water channel, looking upslope. Clear of debris. Functioning as intended.



Image: 3655
Date: 10/21/2019
Time: 1:25 PM
Direction: South

Description:

Vegetation is healthy and present across the entire sideslope. No evidence of erosion, sloughing, or indications of stability issues.



Image: 3659
Date: 10/21/2019
Time: 1:41 PM
Direction: Northeast

Description:

Active area. Well maintained, no ponding water. Material is placed in even lifts that are spread and compacted.



Image: 3661
Date: 10/21/2019
Time: 1:41 PM
Direction: Southeast

Description:

Staking has been placed to represent the location and final target CCR elevation for the next terrace bench. Once final CCR material grades are achieved, final cover will be installed.



Image: 3663
Date: 10/21/2019
Time: 1:43 PM
Direction: Southeast

Description:

Active area. Material is placed in even lifts that are spread and compacted. Some erosion ruts and rills have formed on the active face due to recent rains, but do not affect stability or safety of the landfill.



Image: 3665
Date: 10/21/2019
Time: 1:43 PM
Direction: Northeast

Description:

A non-contact water (stormwater) non-perforated riser, which will be extended to final cover elevation and will accept stormwater after final cover is in place.



Image: 3667
Date: 10/21/2019
Time: 1:45 PM
Direction: Southeast

Description:

Low point in active area. Active face drains to this location, where contact water enters the perforated contact-water (leachate) riser. This riser is wrapped in filter fabric and surrounded with bottom ash.



Image: 3669
Date: 10/21/2019
Time: 1:45 PM
Direction: Southwest

Description:

Active area. Material is placed in even lifts that are spread and compacted. Some erosion ruts and rills have formed on the active face due to recent rains, but do not affect stability or safety of the landfill.



Image: 3671
Date: 10/21/2019
Time: 1:46 PM
Direction: Southwest

Description:

The active area is well maintained with no ponding water. CCR material is spread and rolled shortly after being received.



Image: 3673
Date: 10/21/2019
Time: 1:47 PM
Direction: South

Description:

The active area is well maintained with no ponding water. CCR material is spread and rolled shortly after being received.



Image: 3675
 Date: 10/21/2019
 Time: 1:48 PM
 Direction: Southwest

Description:

Non-contact stormwater pipe along western sideslope. No evidence of erosion or sloughing.

Active area is shown in foreground (spread and compacted bottom ash).



Image: 3677
 Date: 10/21/2019
 Time: 1:49 PM
 Direction: East

Description:

A non-contact water (stormwater) non-perforated riser is shown on the left. This riser will be extended to final cover elevation and will accept stormwater after final cover is in place.

A perforated contact-water (leachate) riser is shown on the right. This riser is wrapped in filter fabric and surrounded with bottom ash.



Image: 3679
Date: 10/21/2019
Time: 1:50 PM
Direction: East

Description:

A perforated contact-water (leachate) riser is wrapped in filter fabric and surrounded with bottom ash.



Image: 3681
Date: 10/21/2019
Time: 1:52 PM
Direction: Northeast

Description:

Sideslope near active face. Vegetation is healthy and present across the entire sideslope. No evidence of erosion, sloughing, or indications of stability issues.



Image: 3683
Date: 10/21/2019
Time: 1:52 PM
Direction: Northeast

Description:

Vegetation on sideslope. Vegetation is well established. No evidence of erosion or sloughing.



Image: 3685
Date: 10/21/2019
Time: 1:56 PM
Direction: Northwest

Description:

Manhole inlet for non-contact water (stormwater), located at the low point on a terrace bench.



Image: 3687
Date: 10/21/2019
Time: 1:56 PM
Direction: Southeast

Description:

Sideslope on bench below active face. Vegetation is healthy and present across the entire sideslope. No evidence of erosion, sloughing, or indications of stability issues.



Image: 3689
Date: 10/21/2019
Time: 1:57 PM
Direction: North

Description:

Typical slope terrace. Terraces are well maintained with no evidence of sloughing or erosion. Vegetation is healthy.



Image: 3691
Date: 10/21/2019
Time: 1:58 PM
Direction: Southeast

Description:

Vegetation on sideslope. Vegetation is well established. No evidence of erosion or sloughing.



Image: 3693
Date: 10/21/2019
Time: 1:59 PM
Direction: North

Description:

Vegetation on sideslope. Vegetation is well established. No evidence of erosion or sloughing.



Image: 3695
Date: 10/21/2019
Time: 2:02 PM
Direction: South

Description:

Vegetation on sideslope. Vegetation is well established. No evidence of erosion or sloughing.



Image: 3697
Date: 10/21/2019
Time: 2:02 PM
Direction: North

Description:

Vegetation is healthy and present across the entire sideslope. No evidence of erosion, sloughing, or indications of stability issues.



Image: 3699
Date: 10/21/2019
Time: 2:03 PM
Direction: Southeast

Description:

Vegetation is healthy and present across the entire sideslope. No evidence of erosion, sloughing, or indications of stability issues.

